


HDL-TM-76-19



AD A 032306

Mechanical Design of the Electronic Turn-On Timer for the M732 Proximity Fuze

September 1976





U.S. Army Materiel Development and Readiness Command HARRY DIAMOND LABORATORIES Adelphi, Maryland 20783 The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Citation of manufacturers' or trade names does not constitute an official indorsement or approval of the use thereof.

Destroy this report when it is no longer needed. Do not return it to the originator.

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered) READ INSTRUCTIONS
BEFORE COMPLETING FORM REPORT DOCUMENTATION PAGE 2. JOVT ACCESSION NO. 1 RECIPIENT'S CATALOG NUMBER HDL-TM-76-19 Mechanical Design of the Electronic Technical Memorandum Turn-On Timer for the M732 Proximity ORG. REPORT NUMBER Fuze! T OR GRANT NUMBER(+) 7. AUTHOR(s) Joseph J. Spellman 1W664602D454 . PERFORMING ORGANIZATION NAME AND ADDRESS PROGRAM ELEMENT, PROJECT, TASK Harry Diamond Laboratories Program Element: 6.4 2800 Powder Mill Road Adelphi, MD 20783 1. CONTROLLING OFFICE NAME AND ADDRESS 12. REPORT DATE September 1976 USA Armament Command Rock Island, IL 61201 MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office) 18. SECURITY CLASS (of this report) Unclassified 184 DECLASSIFICATION/DOWNGRADING 16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) 18. SUPPLEMENTARY HOTES HDL Project: 430665 DRCMS Code: 664602.12.45402 PRON: M165475106M1A9 19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Electronic fuzing Electronic timer 20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The mechanical design of the current electronic turn-on timer for the M732 Artillery Proximity Fuze was developed, and problems arose during its production. An improved mechanical design eliminates most of the production problems of the current timer.

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

1 SECURITY CLASSIFICATION OF THIS PAGE (Then Data Entered)

163050

43

CONTENTS

	Pa	ge
1.	INTRODUCTION	5
2.	MECHANICAL-DESIGN REQUIREMENTS	7
3.	DESCRIPTION OF CURRENT DESIGN	8
4.	DESIGN AND PRODUCTION PROBLEMS	0
5.	DESCRIPTION OF IMPROVED DESIGN	3
6.	CONCLUSIONS	9
	SELECTED BIBLIOGRAPHY	9
	DISTRIBUTION	1
	FIGURES	
1	The M732 Fuze	6
2	Current Timer Design	8
3	Top Plate Assembly	9
4	Timer Board Assembly	0
5	Contact Assembly	1
6	Detonator Socket	2
7	Test Cup Assembly	2
8	Potting Hardware	3
9	Timer Housing Assembly	4
10	Current Timer Assembly	5
11	Detonator Block Assembly	5
12	Thick-Film Ratiometer	6
13	Thin-Film Rationmeter	7
14	Turning Capsule Assembly	8
15	Electronic Assembly	9
16	Improved Timer Design	4
17	Timer Eyelet	5

FIGURES (Cont'd)

		age
18	Detonator Socket Assembly	26
19	Improved Timer Design	27
20	Current and New Timer Designs	28

1. INTRODUCTION

The M732 Artillery Proximity Fuze (fig. 1) was designed for use on all high-explosive (HE) shells fired from 105-, 155-, and 175-mm and 8-in. artillery weapons and from the 4.2-in. mortar. The M732 fuze is called a short-intrusion fuze because it has the same 2.2-ir. intrusion as current point-detonating (PD) fuzes. The present standard proximity fuze, the M728, has an 8.7-in. intrusion. All HE projectiles must therefore be made with a deep cavity to accept the long intrusion. It removable supplementary charge is included in each HE projectile to fill the cavity when a short-intrusion fuze is used. In addition to substantial cost savings from elimination of the supplementary charge, the M732 fuze is expected to be less costly than the M728 fuze and provide better performance.

The electronic turn—on timer in the M732 fuze delays application of battery power to the electronic head until approximately 5 s before the projectile arrives at the target. By delaying turn—on, the electronic timer conserves power—supply energy, decreases the exposure to electronic countermeasures, allows the fuze to be fired closely over obstacles such as hills, and contributes to overhead safety across friendly territory.

In figure 1, the electronic timer is called the timer housing assembly, and the timer-setting element is called the detonator block assembly.

NTIS DOC UNANHOUNCED JUSTIFICATION	White Section Buff Section	1
BY DISTRIBUTION/AV DIST. AVAIL	AILABILITY GOOM	
A		A CONTRACTOR OF THE PROPERTY O

M 732 FUZE CONFIGURATION




Figure 1. The M732 fuze.

692-74

2. MECHANICAL-DESIGN REQUIREMENTS

Most of these mechanical-design requirements are from the M732 fuze requirements document, and the remainder come from experience during the development of other artillery fuzes:

- a. Lowest possible cost
- b. Settability by rotation of the nose of the fuze
- c. Settability in either direction up to 25 times without degradation
- d. Ten years or more storage over the temperature range of -50 to $+70\,^{\circ}\text{C}$ without degradation
- e. Accommodation of the electrical design by providing ready connection and accessibility to test points
- f. Survivability and reliable operation after the following environments:
 - (1) Setback acceleration of 30,000 g
 - (2) Lateral (sideslap) acceleration of 15,000 g
- (3) Seven-foot drop per Test 111, MIL-STD-331, Environmental and Performance Tests for Fuzes and Fuze Components
- (4) Transportation vibration per Test 104, Procedure II, MIL-STD-331
 - (5) Thermal shock per Test 113, MIL-STD-3311
- (6) Humidity per Method 103, Test Condition B, MIL-STD-202, Test Methods for Electronic and Electrical Component Parts²
 - g. Reliable operation during the following environments:
 - (1) Spinning at 500 rps
 - (2) Temperature between -40 and +60°C.

¹MIL-STD-331, Environmental and Performance Tests for Fuzes and Fuze Components, U.S. Department of Defense (10 January 1966).

²MIL-STD-202, Test Methods for Electronic and Electrical Component Parts, U.S. Department of Defense (10 April 1973).

These requirements are severe, but they are necessary to assure reliable, accurate performance in the artillery environment over the military temperature range.

3. DESCRIPTION OF CURRENT DESIGN

The current design is described by the technical data package titled Timer Housing Assembly, 11716959, revision E, dated 5 June 1974. This design underwent development testing and was type classified on 5 February 1976. The electronic operation of the timer is described by Robert I. Christopherson.³

An exploded view of the current design is shown in figure 2. The timer housing and top plate provide the primary structural support with the $18-1b/ft^3$ polyurethane foam used as an encapsulant. The other parts in the timer perform functions such as electrical connections, sealing against potting leakage, electrical insulation, and timing.

TIMER HOUSING ASSEMBLY 11716959




Figure 2. Current timer design.

³Robert I. Christopherson, Proceedings of the Joint Technical Coordinating Group/Air-Launched Non-Nuclear Ordnance Electronic Fuze Symposium (26-27 November 1973).

Fabrication of the timer consists of manufacturing several subassemblies and combining them into the final timer housing assembly. The top plate assembly (fig. 3) consists of the top plate, five insulator bushings, and two groov-pins. The top plate is a 1/16-in.-thick stamped aluminum part. The insulator bushings provide insulation for five wires from the power supply and electronics in the fuze nose, and they seal the top plate and the five feed-through eyelets against potting leakage. The insulator bushings are molded from a tetrafluoroethylene (TFE) type of material (brand name, KEL-F). This material was selected because of its flexibility and heat resistance. When the five wires are soldered to the feed-through eyelets, the insulator bushings must withstand the heat. Two groov-pins align and hold the top plate assembly to the housing. This type of pin was chosen instead of a dowel pin because it does not require a precision hole in the top plate.




Figure 3. Top plate assembly.

The timer board assembly shown in figure 4 consists of a single, custom integrated circuit and assorted electrical components soldered onto a double-sided, plated-through-hole printed-circuit board. The printed-circuit board is designed to minimize errors in time-out caused by leakage currents. The electrical components are placed orthogonally to ease numerically controlled insertion during high-volume production. The five feed-through eyelets are held in position only by being soldered to the printed-circuit board. Three wire standoffs that connect the spring contacts to the timer circuitry protrude from the bottom of the printed-circuit board.




Figure 4. Timer board assembly.

Flaring the contact eyelets to secure the spring contacts to the insulator disc is the final operation in making a contact assembly (fig. 5). The insulator disc was previously cemented into the diecast aluminum housing by using an adhesive preform. The purpose of the adhesive preform is to facilitate handling and to prevent potting leakage. Originally, the insulator disc and insulator bushings were the same material. Because of the high cost of the TFE material, a switch was made to diallyl pthalate material for the insulator disc. .The insulator disc provides mechanical support for the spring contacts and must withstand soldering heat when the wire standoffs are soldered to the contact eyelets and spring contacts. The spring contacts are made of 0.007-in.-thick heat-treated beryllium copper clad with a 0.001-in. precious-metal alloy overlay for the actual contact surface. The spring contacts maintain a force of 50 to 150 grams over the tolerance range of the assembled parts. The structural details of the spring contact have been analyzed (Harry Diamond Laboratories--HDL--laboratory notebook No. 4081, p. 35). Two fingers are used for reliability, and under spin conditions the contact increases slightly (approximately 4 grams at 500 rps) to insure good contact.

The final assembly is started by placing the timer board assembly into the contact assembly. The detonator socket (fig. 6) is inserted into a recess in the insulator disc and through the printed-circuit





Figure 5. Contact assembly.



NOTES:

- 1. MIL-A-2550 APPLIES.
- 2. MATERIAL:
- BODY-COPPER ALLOY NO. 260 HALF HARD IN ACCORDANCE WITH ASTM B 134.
- b. SPRING CONTACT STAINLESS STEEL 302 IN ACCORDANCE WITH ASTM A 313.
- 3. FINISH 1.11.2 of MIL-STD-171 0.000020 THICK MINIMUM.
- 4. APPROVED SOURCE OF SUPPLY: PYLON COMPANY, INC., ATTLEBORO, MA.
- VENDOR PART NO. 2024 S (MODIFIED) OR EQUIVALENT.
- 5. MEASUREMENTS ARE IN INCHES.

Figure 6. Detonator socket.

The detonator socket is flared soldered and the printed-circuit board. Next, the test cup with the test terminal (fig. 7) at its top is centered over the detonator socket and cemented to the printed-circuit board by using a double-sided pressure-sensitive adhesive preform. A wire connecting the test terminal to printed-circuit board is installed and soldered at both ends. The top plate assembly is then pressed on the timer housing. The five insulator bushings fit snugly over the five feed-through eyelets, and the groov-pins fit into shallow half-round recesses in the wall of the timer housing. The assembly is then turned over so the wire standoffs can be soldered to the contact eyelets and spring contacts. Encapsulation




Figure 7. Test cup assembly.

through a hole in the timer housing wall by using 18-lb/ft polyurethane foam is the final operation. The timers are clamped in potting fixtures (fig. 8) with silicone rubber plugs sealing the flanges of the feed-through eyelets and the holes in the timer housing assembly. The encapsulant is injected into the timer housing through a hole in the side wall. The encapsulant consists of two liquid components, which foam after being mixed. The foam cures in about 24 hr at room temperature, but exposing the foam first to 140°F for 2 hr shortens the cure time. Epoxy encapsulants have been tried without success because of electrical characteristics, long cure time, and mechanical deficiencies from -40 to +60°C. Figure 9 shows the timer housing assembly, and figure 10 shows the actual hardware.




Figure 8. Potting hardware.

971-75




Figure 9. Timer housing assembly.




Figure 10. Current timer design.

969-75

The detonator block assembly consists of a detonator block, a ratiometer, and adhesive bonding the two. Figure 11 shows a completed detonator block assembly. Figures 12 and 13 show thick-film and thin-film ratiometers, respectively. The detonator block is machined from steel-bar stock and plated with electroless nickel for corrosion resistance.

To assemble the timer into the fuze, the five wires from the forward portion of the fuze are pushed through the five feed-through eyelets, and the timer housing assembly is pressed onto the body extension. The five leads are then soldered to the feed-through eyelets and clipped to the proper length. Recesses in the side wall of the timer housing are an interference fit with the tangs on the body extension. The tangs transmit torque to drive the timer when the fuze is rotated to set the time. The fuze assembly is called a turning capsule assembly (fig. 14) at this point.

The next step is to place a detonator block assembly into the fuze sleeve with a holding ring. The turning capsule assembly is then pressed into the sleeve mating the hub of the detonator block assembly with the hole in the timer. The turning capsule assembly is secured by tightening four setscrews against the split retaining ring. The holding ring is then tightened, clamping the detonator block assembly against the timer. Epoxy on the threads fastens the holding ring to the fuze sleeve. The fuze assembly at this point is called an electronic assembly (fig. 15).





Figure 11. Detonator block assembly.

968-75



720-75-2

Figure 12. Thick-film ratiometer.




Figure 13. Thin-film ratiometer.

788-73





Figure 14. Turning capsule assembly.



5. TURNING CAPSULE ASSEMBLY AND SLEEVE SHALL BE ANGULARLY ALIGNED BY USING ALIGNMENT IFTURE IT INDEADS ALIGNMENTED TRYING IT INDEADS ALIGNMENTED TRYING IT INDEADS ALIGNMENTED TRYING IT INDEAD TO BRING MAN 5 ONE ROTALING CONTRIBLY DROUGHOUS PROBLEM TO BE REFIGICATED THING AND CONDELARLY DROUGHOUS POWER THE ASSEMBLY CONDER THE CONTINUOUSLY ON ONE LASHING. ROTALE DITONALOR SLOCK ASSEMBLY CONCURS THE LASHING INDICATOR TARM DISTOLORS OFF IN THIS POSITIONS STARLY CONCURS THE LASHING INDICATOR TARM DISTOLORS OFF IN THIS POSITIONS STARLY CONCURS THE CONTINUOUSLY ON ONE LASHING TO HOLDING RING WITHOUT HOUSING SHALL WITHSTAND TORQUE OF 55 °5 IN -LB IN EITHER DIRECTION WITHOUT HOUSING CONTRIBUTION OF SETTING SACTOR OF SETTING RATIOMETER AND SETTING RATIOMETER

Electronic assembly. Figure 15. After setting the turning capsule assembly to the zero alignment position on the sleeve, a small (0.035-in. o.d.) coaxial probe is inserted through the hole in the detonator block into the timer through the detonator socket. The outside sheath of the probe contacts the detonator socket, and the center conductor of the probe contacts the timer test point. The detonator block assembly is rotated by using two holes in the bottom while the timer electronics are being powered through the test point. When the electrical zero alignment point is sensed, the flange on the detonator block is crimped into the slots in the holding ring. The physical end of the setting resistor on the ratiometer is the electrical zero alignment point. The zero alignment could be done mechanically, but inaccuracy would result from mechanical tolerance buildup that is eliminated by electrical sensing after the parts are assembled. Loading of explosives completes the fuze assembly.

4. DESIGN AND PRODUCTION PROBLEMS

Three approaches were employed to solve the design and production problems that arose. First, the part or assembly was redesigned. Second, the production method was modified. Third, as a last resort, stringent controls were placed on the production method. Later, the timer was completely redesigned. The following problems with the current timer design are in approximate chronological order.

Problem 1. -- The foam potting leaked where it was not wanted.

Solution.—The insulator bushings sealed the feed-through eyelets on one end and sealed the top plate holes where the wires from the fuze entered. Adhesive bonded the insulator disc to the housing. The rubber plugs and pins (fig. 8) sealed the flanges of the feedthrough eyelets and the holes in the timer housing. The rubber plugs were a continuing problem. They could be used only a few times before they had to be discarded, and they were difficult to manufacture. Cleaning foam potting from timers and the potting molds was a laborious hand operation. The technique and fixtures currently used for foam potting were adequate, but time consuming.

<u>Problem 2.--The timers</u> failed to work after they were assembled to the <u>fuzes</u> and the five wires were soldered.

Solution.--Originally, double-sided printed-circuit boards without plated-through holes were used in timers. Soldering the feed-through eyelets on both sides of the printed-circuit board connected the sides. Soldering the five feed-through wires at the fuze assembly resulted in solder reflow at the timer printed-circuit board. Also, because a dull drill had been used to drill holes in the printed-circuit board, a chamfering tool had been applied to each hole to clean up the burrs

caused by the dull drill. This cleanup operation left an insulating ring around the hole in the center of each printed-circuit board pad. This insulating ring was bridged when the feed-through eyelets were soldered to the printed circuit, but when reflow occurred later in the fuze assembly, an open circuit connection resulted. Two courses of action were followed to eliminate this problem. The first was to change to a plated-through-hole type of printed-circuit board to provide a more reliable connection between both sides, even if solder reflow occurred. The second was to specify a low-melting-point solder for soldering the five wires to the feed-through eyelets to minimize possible solder reflow at the timer printed-circuit board.

<u>Problem 3.--</u>The cadmium plating on the detonator block was flaking off and found lying on the ratiometer. These pieces of metal could short the ratiometer and affect timer performance.

Solution. -- The anodizing of the timer housing gave it an extremely hard and abrasive surface. At the five holes where the feed-through eyelet connections were made, the edges of the holes were scraping the cadmium plating off the detonator block. The anodizing of the timer housing could not be changed readily. Several platings were tried on the detonator block, and electroless nickel was selected because it did not flake off or wear when rotated against the anodized timer housing.

<u>Problem 4.--</u>The insulator bushings molded by an outside vendor were brittle, discolored, and unacceptable.

Solution. -- The HDL molding of the insulator bushings was successful. When The General Electric Company (GE) attempted to buy insulator bushings from a commercial vendor, he could not deliver acceptable parts. The commercial vendor was using the sprues, etc., from each mold cycle together with virgin material. The HDL practice is never to use anything except virgin material. Commercial practice is to reuse scrap with virgin material to lower cost. This TFE material responds unfavorably to being reused and requires close temperature control even if only virgin material is being used. Because the commercial vendor was unsuccessful, GE had the parts made on a screw machine using molded bar stock of virgin TFE. In the future, molding of these parts will require that HDL keep in close contact with a molding vendor to insure a quality product.

<u>Problem 5.--After exposure to +60°C</u>, the top plates were lifted as much as 1/16 in. above the timer housing. This rise caused the timer to fail the height specification.

Solution. -- Growth of the polyurethane foam encapsulation was the cause of top plate lifting. An incomplete cure caused by an improper ratio between the two components of the foam potting was suspected as

the cause. But HDL tests did not substantiate this theory. A 2- to 4-hr soak at +70°C with the timer clamped in the potting fixture solved the problem. Timers that had foam potting cured by this method did not exhibit top plate lifting during later temperature exposure. It was suspected that the liberal use of methyl-ethyl-ketone (MEK) solvent to clean off foam potting after removal of the timer from the potting fixtures was contributing to the problem. Careful use of MEK was ordered. These changes eliminated this problem.

Problem 6.--Test cup terminals (fig. 7) were received locked in pairs. They could be separated only with difficulty, causing a lot of unnecessary work.

<u>Solution</u>.--The problem resulted from the intermeshing of two terminals because the slot dimension was slightly larger than the fingers. During barrel plating, the two parts became plated together and difficult to separate. The solution was to change the dimensions of the part so that the fingers and slot could not fit together.

<u>Problem 7.--The timers were observed to have cracked insulator discs</u> where the detonator block mated with the timer.

Solution. -- An inexperienced operator had pressed the test cup too forcefully onto the printed-circuit board. A stop was added to the assembly tooling to eliminate this problem.

Problem 8.--Flaring of the detonator socket split the wall of the socket.

Solution.--A 60-deg flare had been specified on the drawing. Tests at HDL showed that a 30-deg flare was adequate. Examination of the detonator sockets showed that they were made from harder material than the drawing specified, and the hole was not concentric with the outside diameter, drastically decreasing the wall thickness. The problem was solved by using the 30-deg flare and having the vendor replace the detonator sockets with eccentric holes.

<u>Problem 9.--After</u> assembly and encapsulation, timer housing assemblies or timer housings alone did not pass the outside-diameter gage test.

Solution. The timer housings were manufactured in a bell-mouth condition. Since they had been received and anodized, nothing could be done quickly except sorting out the ones that would not fit through the gage. The groov-pins in the top plate were spreading the housing so that the unit did not fit through the gage. A fixture was made that squeezed the unpotted timer housing assembly to the proper dimension. The solution was time consuming, but effective.

<u>Problem 10.--Flaring the contact</u> eyelet sheared it off against the edge of the spring contact.

Solution. -- The spring contact is a stamped metal part with sharp edges. In the hole of the spring contact, they were shearing the contact eyelet when it was flared to secure the spring contact. Control of the flaring angle and pressure solved this problem.

<u>Problem 11.--Adhesive</u> used to bond the insulator disc was observed in the center hole of the timer housing.

Solution. -- The hole in the adhesive preform was enlarged and the pressure was controlled to minimize squeeze out.

<u>Problem 12</u>.--Body extensions manufactured by the fuze contractor did not mate with timer housing assemblies.

Solution. -- The body extensions were defective in manufacture. Since the defective body extensions were already on fuzes, it was decided that modification of the timer housing assemblies would be the easiest way to solve the problem. A chamfer was filed on each edge of the notches in the top plate where the tangs on the body extension passed through. This modification allowed the defective body extensions to be used until the fuze manufacturer could procure acceptable material.

Problem 13.--X raying timer housing assemblies showed that some had wire clippings inside.

Solution.—The first explanation from the contractor was that the inspected units were across the bench from lead clipping operations and that some clippings apparently had landed on the already inspected units. A rearrangement of the assembly and inspection stations eliminated the problem. A second occurrence of this problem was found to be from the wire jumper from the test point to the printed-circuit board. This jumper probably caused the problem the first time, also. Careful inspection before foam potting was the only solution to this problem.

5. DESCRIPTION OF IMPROVED DESIGN

The new design is described by the technical data package titled timer assembly, dated 14 December 1973.

An exploded view of the improved timer design is shown in figure 16. The design and production problems with the current configuration have been almost totally eliminated by the new, improved design. It has approximately half the parts count of




Figure 16. Improved timer design.

for mechanized assembly, and will cost much less (HDL laboratory notebook No. 4595, p. 37). A contract was awarded to implement the detailed design and to fabricate the parts. Samples of the new design have been manufactured and tested. Analysis of these limited test data indicates that this improved design should easily meet the timer requirements. Approximately 2000 timers are currently being built into fuzes for field testing and evaluation.

The timer housing and cover still provide the primary structural support together with the polyurethane foam potting encapsulant. The timer housing is injection molded by using 40-percent glass-filled polycarbonate material. This eliminates many parts of the current design, the five feed-through eyelets can be sealed, and the raised walls around the spring contacts protect them from handling damage. Three contact terminals are inserted and ultrasonically bonded into the timer housing to provide electrical and mechanical connection to the spring contacts and printed-circuit board.


⁴Product Improvement of the XM732 Electronic Timer, Final Technical Report, General Electric Co., Aerospace Electronic Systems Department, under contract DAAG-73-C-0087, Utica, NY (January 1974).

The new timer cover is an injection-molded part of the same material as the timer housing. The insulator-bushing function is now part of the top cover. The five feed-through eyelets are swaged slightly in the holes in the top cover to be sealed against potting leakage.

Figure 17 shows the new feed-through eyelet. It has a flange to locate its height on the printed-circuit board. It is designed also to be swaged out against the timer housing and cover, to seal against potting leakage. The eyelet and timer housing are designed also to accommodate automatic welding of the five wires from the fuze, instead of the present method of hand soldering.

A new part (fig. 18) was designed to replace the current costly detonator socket and test cup assembly and adhesive. The test-point terminal and wire jumper to the printed-circuit board are all part of the detonator socket assembly.


For cost reduction, a switch was made to a printed-circuit board by the additive instead of the subtractive process. A low temperature coefficient, thick-film, laser-trimmed resistor was substituted for the 2-megohm timing resistor and the trim resistor used in the current design.



NOTES

- 1. MIL-A-2550 APPLIES
- 2. MATERIAL: NICKEL ALLOY TUBING IN ACCORDANCE WITH MIL-N-19153.
- 3. FINISH: 1.8.1 OF MIL-STD-171, 0.00015 IN. THICK.
- MEASUREMENTS ARE IN INCHES. PREVIOUS SOURCE OF SUPPLY: AMP INC. HARRISBURG, PA

Figure 17. Timer eyelet.



- 1. CONTACT INSERTION FORCE: WHEN TESTED WITH SPHERICAL NOSE GAGE PINS. THE INSERTION FORCE SHALL BE 50 GRAMS MIN WITH 0.0300 ± 0.0003 DIAM PIN AND 250 GRAMS MAX WITH 0.0350 ± 0.0003 DIAM PIN.
- 2. ITEM IDENTIFICATION MARKING SHALL BE IN ACCORDANCE WITH MIL-STD-130.
- 3. $\frac{0.110}{0.102}$ DIMENSION TO BE WITH STEEL PIN INSERTED PER NOTE 1.
- 4. MEASUREMENTS ARE IN INCHES. PREVIOUS SOURCE OF SUPPLY: AMP INC. HARRISBURG, PA

Figure 18. Detonator socket assembly.

The assembly of the new design is simple. First, the three contact terminals are inserted and ultrasonically bonded into the timer housing. The printed-circuit board assembly including the detonator socket assembly is placed into the housing. The three contact terminals are flared and soldered to the printed-circuit board. The detonator socket assembly is flared against the timer housing. The spring contacts are placed on the contact terminals, which are flared and soldered to the spring contacts. The top cover is cemented to the housing with epoxy, and the five feed-through eyelets are swaged against the holes in the cover to seal against potting. (Ultrasonic bonding of the cover was attempted. It was not satisfactory because the ultrasonic energy was transmitted down the feed-through eyelets through the timer circuitry into the integrated circuit and burned out the integrated circuit.) The final operation is to encapsulate the timer assembly through a hole in the top cover. This can be done in the new design without the need for fixtures or sealing plugs.

The detonator block assembly was improved by making the recess shallower. This depth stiffens the detonator block, providing better support for the ratiometer. Cadmium plating can again be used instead of more costly electroless nickel, because the plastic housing does not abrade the cadmium plating.

The new timer assembly (fig. 19) and detonator block assembly are assembled into the fuze exactly as in the current design. The molded top cover of the new design has a chamfer molded in so that if the body extension is defective in this area, it can still be used. The slots in the new design are 180 deg apart to simplify manufacture of the body extension tangs by having them in line. The five wires from the fuze to the feed-through eyelets can be welded with the new design. Slots are provided in the timer housing for access by welding electrodes.

The current and new timer assemblies can be compared in figure 20.




Figure 19. Improved timer design.

970-75



CURRENT



TIMER HOUSING



NEW




CURRENT




NEW

TOP COVER



CURRENT



NEW

PRINTED CIRCUIT BOARD

336-74

Figure 20. Current and new timer designs.

6. CONCLUSIONS

The current design has performed well, demonstrating over 98-percent reliability during actual gun firings. The improved design should improve this performance at a much lower cost.

SELECTED BIBLIOGRAPHY

Final Technical Report, An Integrated Electronic Timer, General Electric Co., Semiconductor Products Department, under contract DAAG39-67-C-0016, Syracuse, NY (October 1968).

Final Technical Report, Conductive Plastic Summary Report, Production Engineering Measure for Mechanized Production and Test Equipment for Time Setting Potentiometers (Cermet and Conductive Plastic), Globe-Union, Inc., CENTRALAB Electronics Division, under contract DAAB05-71-C-2638, Milwaukee, WI (July 1973).

Final Technical Report, Design Concept of the Mechanized Assembly Line for the XM732 Electronic Timer, General Electric Co., Aerospace Electronic Systems Department, under contract DAAG39-74-C-0014, Utica, NY (December 1973).

Final Technical Report, Precision Adjustable Electronic Timer, Fairchild Camera and Instrument Corp., Semiconductor Division, under contract DAAG39-71-C-0006, Mountain View, CA (August 1972).

Final Technical Report, Product Improvement of a Fail-Safe Electronic Analog Turn-On Timer, General Electric Co., Semiconductor Products Department, under contract DAAG39-70-C-0055, Syracuse, NY (October 1971).

Final Technical Report, Production Engineering Measure for Mechanized Production and Test Equipment for Time Setting Potentiometers (Cermet), Globe-Union, Inc., CENTRALAB Electronics Division, under contract DAAB05-71-C-2638, Milwaukee, WI (October 1974).

Final Technical Report, Production Engineering Measure for Thin Film Ratiometer, TRW, Inc., under contract DAAB05-73-C-2077, Philadelphia, PA (August 1975).

Final Technical Report, Production of Electronic Timer P/N 11716959, General Electric Co., Integrated Circuit Products Department, under contract DAAG39-71-C-0048, Syracuse, NY (May 1972).

Final Technical Report, Production of Integrated Electronic Timer P/N 11716959, General Electric Co., Aerospace Electronic Systems Department, under contract DAAG39-72-C-0114, Utica, NY (September 1972).

Final Technical Report, Production of XM732 Electronic Timers, General Electric Co., Aerospace Electronic Systems Department, under contract DAAG39-73-C-0188, Utica, NY (July 1974).

Kitchman, L. A., Swirczynski, J. P., Hebb, E. L., Wood, G. B., and Bullis, L. H., Design and Fabrication of a Thin-Film Ratiometer for Electronic Timer of XM732 Proximity Fuze, Harry Diamond Laboratories TM-74-24 (December 1974).

Value Engineering Task Force Report--XM732 Proximity Fuze, Harry Diamond Laboratories (1 June 1972).

DISTRIBUTION

DEFENSE DOCUMENTATION CENTER CAMERON STATION, BUILDING 5 ALEXANDRIA, VA 22314 ATTN DDC-TCA (12 COPIES)

COMMANDER
USA RSCH & STD GP (EUR)
BOX 65
FPO NEW YORK 09510
ATTN LTC JAMES M. KENNEDY, JR.
CHIEF, PHYSICS & MATH BRANCH

COMMANDER
US ARMY MATERIEL DEVELOPMENT
6 READINESS COMMAND
5001 EISENHOWER AVENUE
ALEXANDRIA, VA 22333
ATTN DRXAM-TL, HQ TECH LIBRARY
ATTN DRCDE, DEV 6 ENGR. DIRECTORATE
ATTN DRCPF-W, ARMAMENTS DIV.

COMMANDER
USA ARMAMENT COMMAND
ROCK ISLAND, IL 61201
ATTN DRSAR-ASF, FUZE DIV
ATTN DRSAR-RDF, SYS DEV DIV - FUZES

COMMANDER
USA MISSILE & MUNITIONS CENTER & SCHOOL
REDSTONE ARSENAL, AL 35809
ATTN ATSK-CTD-F

OFFICE, CHIEF OF RESEARCH, DEVELOPMENT 6 ACQUISITION DEPARTMENT OF THE ARMY WASHINGTON, DC 20310 ATTN DAMA-AB, DIRECTOR ARMY RESEARCH ATTN DAMA-DD, DIRECTOR, DEVELOPMENT

DIRECTOR
DEFENSE RESERACH AND ENGINEERING
THE PENTAGON
WASHINGTON, DC 20301
ATTN LIBRARY (TECHNICAL), 3C-128

ARMY ADVANCED BALLISTICS MISSILE DEFENSE AGENCY P. O. BOX 5474 RIVERSIDE, CA 92507 ATTN TECH DIRECTOR

COMMANDER
USA BALLISTICS RESEARCH LABORATORIES
ABBENDEN PROVING GROUND, MD 21005
ATTN STEAP-TL, TECHNICAL LIBRARY
DIVISION (2 COPIES)
ATTN TECHNICAL LIBRARY, BLDG 313

COMMANDER
U. S. ARMY MOBILITY EQUIPMENT RESEARCH
6 DEVELOPMENT CENTER
FORT BELVOIR, VA 22060
ATTN STSFB-W, TECH LIB

COMMANDER U. S. ARMY WEAPONS COMMAND ROCK ISLAND, IL 61201 ATTN LIBRARY

COMMANDER
U. S. ARMY MATERIALS & MECHANICS
RESEARCH CENTER
WATERTOWN, MA 02172
ATTN TECHNICAL INFORMATION CENTER

COMMANDER
YUMA PROVING GROUND
YUMA PROVING GROUND, AZ 85364
ATTN STEYP-TE, TEST 6
EVALUATION DIRECTORATE

COMMANDER U. S. ARMY RESEARCH OFFICE (DURHAM) P. O. BOX 1221 TRIANGLE RESEARCH PARK, NC 27709 ATTN CRD-AA-IP

COMMANDER
EUSTIS DIRECTORATE
USA AIR MOBILITY RSCH
& DEV LAB
FORT EUSTIS, VA 23604
ATTN DIRECTOR, R&D

COMMANDER NAVAL SURFACE WEAPONS CENTER WHITE OAK, SILVER SPRING, MD 20910 ATTN TECHNICAL LIBRARY, 1-315

DEPARTMENT OF THE NAVY
ORDNANCE SYSTEM COMMAND
WASHINGTON, DC 20360
ATTN DLI-3, TECHNICAL LIBRARY

DIRECTOR
NAVAL RESEARCH LABORATORY
WASHINGTON, DC 20390
ATTN CODE 2620, TECH LIBRARY
ATTN CODE 2027, LIBRARY
ATTN CODE 2029, (ONEL)

COMMANDER
NAVAL WEAPONS CENTER
CHINA LAKE, CA 93557
ATTN TECH LIBRARY
ATTN CODE 406, TECH LIB

COMMANDER U. S. NAVAL SURFACE WEAPONS CENTER DAHLGREN, VA 22448 ATIN LIBRARY

DIRECTOR U. S. NAVAL ELECTRONICS LABORATORY CENTER SAN DIEGO, CA 92152

U. S. NAVAL ACADEMY ENGINEERING DEPT ANNAPOLIS, MD 21402 ATTN LIBRARY

COMMANDER NAVAL UNDERSEA CENTER SAN DIEGO, CA 92152

COMMANDER U. S. NAVAL AIR DEVLEOPMENT CENTER WARMINSTER, PA 18974 ATTN NADC LIBRARY

COMMANDER
U. S. NAVAL MISSILE CENTER
POINT MUGU, CA 93041
ATTN TECHNICAL LIBRARY, CODE NO322

COMMANDER
ARMAMENT DEVELOPMENT AND
TEST CENTER
EGLIN AFB, FL 32542

COMMANDER ARNOLD ENGINEERING DEVELOPMENT CENTER ARNOLD AIR FORCE STATION, TN 37389 ATTN LIBRARIAN

AF OFFICE OF SCIENTIFIC RESEARCH 1400 WILSON BLVD ARLINGTON, VA 22209 ATTN LIBRARIAN

COMMANDER U. S. ARMY MISSILE COMMAND FRANKFORD ARSENAL PHILADELPHIA, PA 19137 ATTN J4000, ARTILLERY AMMUNITION LAB ATTN K1000, TECHNICAL LIBRARY, 0270

COMMANDER
PICATINNY ARSENAL
DOVER, NJ 07801
ATTN SARPA-SCIENTIFIC 6 TECHNICAL
INFORMATION BRANCH
ATTN F. SAXE

COMMANDER
EDGEWOOD ARSENAL
EDGEWOOD ARSENAL, MD 21010
ATTN TECHNICAL LIBRARY

U. S. LIBRARY OF CONGRESS SCIENCE & TECHNOLOGY DIVISION WASHINGTON, DC 20540

NATIONAL BUREAU OF STANDARDS WASHINGTON, DC 20234 ATTN LIBRARY

BOULDER LABORATORIES NATIONAL BUREAU OF STANDARDS BOULDER, CO 90302 ATTN LIBRARY

SANDIA LABORATORIES P. O. BOX 5800 ALBUQUERQUE, NM 87115 ATTN TECHNICAL LIBRARY

SANDIA LABORATORIES LIVERMORE LABORATORY P. O. BOX 969 LIVERMORE, CA 04550 ATTN TECHNICAL REFERENCE LIBRARY

DIRECTOR LAWRENCE RADIATION LABORATORY P. O. BOX 1663 LOS ALAMOS, NM 87544 ATTN LIBRARIAN

JET PROPULSION LABORATORY 4800 OAK GROVE DRIVE PASADENA, CA 91103 ATTN LIBRARY, TDS- N. E. DEVERAUS

NATIONAL ACADEMY OF SCIENCES NATIONAL RESEARCH COUNCIL COMMITTEE ON UNDERSEA WARFARE 2101 CONSTITUTION AVENUE, N. W. WASHINGTON, DC 20418

NATIONAL AERONAUTIC AND SPACE ADMINISTRATION LEWIS RESEARCH CENTER 21000 BROOKPARK ROAD CLEVELAND, OH 44135 ATTN MR. GEORGE MANDEL, CHIEF, LIBRARY

DISTRIBUTION (Cont'd)

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION GODDARD SPACE FLIGHT CENTER GREENBELT, MD 20771 ATTN LIBRARY

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION LANGLEY RESEARCH CENTER LANGLEY STATION HAMPTON, VA 23365 ATTN LIBRARY, MS 185

NASA SCIENTIFIC AND TECHNICAL INFORMATION FACILITY P. O. BOX 33 COLLEGE PARK, MD 20740 ATTN NASA REPRESENTATIVE (SAK/DL)

COMMANDER NATICK LABORATORIES NATICK, MA 01762 ATTN DIRECTOR, R&D

FRANKLIN INST RESEARCH LABS 20th & BENJAMIN FRANKLIN PARKWAY PHILADELPHIA, PA 19103 ATTN TECHNICAL DIRECTOR

UNIVERSITY OF PITTSBURGH ORDNANCE RESEARCH STAFF 520 DUPONT CIRCLE BLDG 1345 CONNECTICUT AVENUE, NW WASHINGTON, DC 20036 ATTN F. GORDON BARBER

STANFORD RESEARCH INSTITUTE ATTN SECURITY OFFICER 333 RAVENWOOD AVENUE MENLO PARK, CA 94025

DIRECTOR ORDNANCE RESEARCH LABORATORY PENNSYLVANIA STATE UNIVERSITY P. O. BOX 30 STATE COLLEGE, PA 16801

SUPERINTENDENT
NAVAL POSTGRADUATE SCHOOL
MONTEREY, CA 93940
ATTN LIBRARY, CODE 2124

SYSTEMS, SCIENCE AND SOFTWARE P. O. BOX 1620 LA JOLLA, CA 92037 ATTN LIBRARIAN

GENERAL MOTORS TECHNICAL CENTER WARREN, MI 48090 ATTN LIBRARIAN

BOEING COMPANY, THE RESEARCH AND ENGINEERING DIV SEATTLE, WA 98100 ATTN LIBRARIAN MARTIN MARIETTA CORP AEROSPACE DIV P. O. BOX 5837 M. D. 109 ORLANDO, FL 32805 ATTN LIBRARIAN

NORTH AMERICAN AVIATION INC SPACE AND INFORMTION SYSTEMS DIVISION DOWNEY, CA 90241 ATTN TECHNICAL INFORMATON CENTER D/096-722 (AJO1)

GENERAL ELECTRIC COMPANY AESD FRENCH ROAD UTICA, NY 13503 ATTN MR. J. COUZELIS

IIT RESEARCH INSTITUTE 10 W. 35TH STREET CHICAGO, IL 60616 ATTN LIBRARIAN

HARRY DIAMOND LABORATORIES
ATTN MCGREGOR, THOMAS, COL, COMMANDING
OFFICER/FLYER, I.N./LANDIS, P.E./
SOMMER, H./CONRAD, E.E.
ATTN CARTER, W.W., DR., ACTING TECHNICAL
DIRECTOR/MARCUS, S.M.
ATTN KIMMEL, S., 10
ATTN CHIEF, 0021
ATTN CHIEF, 0022
ATTN CHIEF, LAB 100
ATTN CHIEF, LAB 200
ATTN CHIEF, LAB 300
ATTN CHIEF, LAB 300
ATTN CHIEF, LAB 500
ATTN CHIEF, LAB 600
ATTN CHIEF, LAB 600
ATTN CHIEF, LAB 600
ATTN CHIEF, DIV 800
ATTN CHAIRMAN, EDITORIAL COMMITTEE
ATTN CHIEF, 047
ATTN TECH REPORTS, 013
ATTN PATENT LAW BRANCH, 071
ATTN MCLAUCHLIN, P.W., 741
ATTN MCLAUCHLIN, P.W., 741
ATTN MCLAUCHLIN, P.W., 741
ATTN BARRON, M. A., 430
ATTN CHRISTOPHERSON, R. I., 650
ATTN CHRISTOPHERSON, R. I., 650

ATTN CHIEF, 047
ATTN TECH REPORTS, 013
ATTN TECH REPORTS, 013
ATTN PATENT LAW BRANCH, 071
ATTN MCLAUGHLIN, P.W., 741
ATTN APOLENIS, C. J., 750 (10 COPIES)
ATTN BARRON, M. A., 430
ATTN CHRISTOPHERSON, R. I., 650
ATTN DRAKE, J. L., 680
ATTN DRAKE, J. L., 680
ATTN DRAKE, J. L., 480
ATTN FINGER, D. W., 440
ATTN JACOBS, M. E., 440
ATTN JACOBS, M. E., 440
ATTN MILCHMAN, L. A., 910
ATTN KITCHMAN, L. A., 910
ATTN KROP, R. G., 721
ATTN MCLAUGHLIN, P. W., 741
ATTN MILLER, J. W., 581
ATTN SUMINSKI, H., 750
ATTN SUMINSKI, H., 750
ATTN WILLIAMS, D., 910
ATTN WILLIAMS, D., 910
ATTN WILLIAMS, D., 910
ATTN SPELLMAN, J. J., 0021 (20 COPIES)